



Picture 1 – Visser Brothers Farm, 2620 Panton Rd., New Haven, VT – 06/26/14
Manure pit at the main farm.



Picture 2 – Visser Brothers Farm, 2620 Panton Rd., New Haven, VT – 06/26/14
Extent of the heavy use area/pasture from the main farm to Dead Creek.



Picture 3 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Fence damage, bank erosion, and evidence of cow traffic at the edge of Dead Creek.



Picture 4 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Clean water diversion pipe discharge location, with cow hoof prints and bones in the area.



Picture 5 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
West side of the silage bunkers (looking north toward the heifer farm).



Picture 6 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Location where runoff from the west side of the silage bunkers enters the manure pit.




Picture 7 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Northeast side of the silage bunkers.




Picture 8 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Southeast side of the silage bunkers.



Picture 9 – Visser Brothers Farm, 2620 Panton Rd., New Haven, VT – 06/26/14
Vegetated drainage swale that receives runoff from the southeast side of the silage bunkers.



Picture 10 – Visser Brothers Farm, 2620 Panton Rd., New Haven, VT – 06/26/14
Location where silage runoff from the vegetated drainage swale enters a dirt ditch.



Picture 11 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Drainage ditch flowing south toward Dead Creek.



Picture 12 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Drainage ditch entering a wetland bordering Dead Creek.



Picture 13 – Visser Brothers Farm, 2620 Panton Rd., New Haven, VT – 06/26/14
Heifer exercise lot at the main barn, located southwest of the barns.



Picture 14 – Visser Brothers Farm, 2620 Panton Rd., New Haven, VT – 06/26/14
Water at the end of the exercise lot in picture #13.



Picture 15 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Manure transfer area from the heifer barn on Stove Pipe City Rd.



Picture 16 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Location where heifer barn manure is transferred across Pantan Road (looking north).



Picture 17 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Location where heifer barn manure is transferred into the manure pit (looking south).



Picture 18 – Visser Brothers Farm, 2620 Pantan Rd., New Haven, VT – 06/26/14
Water pooling at the heifer farm on Stove Pipe City Rd.



Picture 19 – Visser Brothers Farm, 2620 Panton Rd., New Haven, VT – 06/26/14
Roadside ditch on Stove Pipe City Rd. that receives runoff from the heifer farm.



Picture 20 – Visser Brothers Farm, 2620 Panton Rd., New Haven, VT – 06/26/14
Bedding pile on a concrete pad at the heifer farm on Stove Pipe City Rd.